

Accuracy	+0.2 degrees	Response time	0.5s
Abnormal automatic alarm	Flashing +"Di Di" sound	Charging Method	USB Charging or Battary
Automatic Measurement	Measuring Distance 5cm - 10cm	Input	USB DC 4.2-5V
Standby	About One Week	Weigth	350g
Install Method	Nail Hook,Double-sided Adhesive Sticking, Bracket Fixing	Dimensions	170**115*140mm
Operating Temperature	10 °C - 40 °C (Recommend) 15 °C- 35 °C	Infared Measuring Range	0~50 °C
Standby	5s (Red dot dynamic Cycle)	Screen	Digital Display

Quick Measurement

Accurate Feedback

Fever Alarm

www.snappy.ae

FC (E RoHS Z